




VACUUM HARNESS ASM.
Part No. 599613

001197



001490



691199

Dual Function: Coolant Temperature Override (CTO)

TWS	N	1	M	Source of Variation
Parallels				
Source of measure	L	2	K	^{full range} of polygamies (poly ergo)
	S	3		Filled Variance used

FC	101	140°
STO	12° 18'	150° 160°
FO	121'	170°

ECB value function controlled by Thermal Vacuum Silda (TVS) which measures air clean air temperature and the fuel function Control Temperature Deviate (CTD) which measures manifold coolant temperature.

F60 value

501260






Figure 1-11 Intake and Exhaust ManHolds
AM General



843 3000 719

100100

FJ8C ENGINE ELECTRICAL WIRING HARNESS S995769-R

CKT NO.

CIRCUIT DESCRIPTION

1J + chassis harness connector to manifold heater relay switch

3C + chassis harness connector to splice #5

3D + splice #5 to MCU (pin 58)

3E + splice #5 to ignition module

3F + splice #5 to diagnostic connector (1-4)

4J + chassis harness connector to splice #4

4K + splice #4 to MCU (pin 1)

4L + splice #4 to MCU (pin 57)

4M + splice #4 to triple solenoid

4N + splice #4 to ignition module

4P + splice #4 to diagnostic connector (2-4)

4Q + splice #4 to PCV shut-off solenoid

4R + splice #4 to stepper motor

5F + chassis harness connector to idle relay switch

99A - engine ground to MCU (pin 17)

99B - engine ground to splice #1

99C - splice #1 to coolant temperature switch

99D - splice #1 to diagnostic connector (2-7)

99E - splice #1 to wide open throttle switch

99F - splice #1 to diagnostic connector (1-3)

99G - splice #1 to thermal electric switch

99H - splice #1 to splice #2

99J - splice #2 to high altitude jumper

99K - splice #2 to idle relay (diode)

99L - splice #2 to vacuum switch assembly

99M - splice #2 to MCU (pin 20)

99N - splice #2 to MCU (pin 60)

26B + chassis harness connector to idle relay solenoid

29B + temperature gauge sending unit to chassis harness connector

33A - MCU (pin 43) to idle relay solenoid

33B - idle relay solenoid to diagnostic connector (2-15)

34B + chassis harness connector to splice #6

34C + splice #6 to diagnostic connector (1-2)

34D + splice #6 to electric choke

34E + splice #6 to manifold heater relay solenoid

35A - MCU (pin 45) to upstream vacuum solenoid

35B - upstream vacuum solenoid to diagnostic connector (2-8)

36A - MCU (pin 46) to downstream vacuum solenoid

36B - downstream vacuum solenoid to diagnostic connector (2-5)

38A - diagnostic connector (1-6) to MCU (pin 54)

38B - wide open throttle switch to diagnostic connector (1-6)

001202

39A - PCV shut-off solenoid to diagnostic connector (2-1)
 39B - MCU (pin 41) to PCV shut-off solenoid
 40A - MCU (pin 50) to stepper motor
 41A - MCU (pin 48) to diagnostic connector (2-11)
 41B - diagnostic connector (2-11) to stepper motor
 42A - MCU (pin 49) to stepper motor
 43A + manifold heater relay switch to manifold heater
 44A - manifold heater switch to manifold heater relay solenoid
 45B - splice #7 to chassis harness connector
 45C - splice #7 to diagnostic connector (1-1)
 45D - ignition module to splice #7
 46A - distributor ground to ignition module
 47A + ignition module to MCU (pin 47)
 48A + MCU (pin 59) to distributor
 49A - MCU (pin 18) to distributor
 50A - knock sensor to MCU (pin 51)
 51A - diagnostic connector (2-14) to stepper motor
 51B - MCU (pin 10) to diagnostic connector (2-14)
 52A - coolant temperature switch to diagnostic connector (2-12)
 52B - diagnostic connector (2-12) to MCU (pin 56)
 53A - O₂ sensor to splice #3
 53B - splice #3 to MCU (pin 9)
 53C - splice #3 to MCU (pin 8)
 54A - thermal electric switch to diagnostic connector (2-10)
 54B - diagnostic connector (2-10) to MCU (pin 53)
 55A - diagnostic connector (2-9) to MCU (pin 55)
 55B - vacuum switch assembly to diagnostic connector (2-9)
 56A - diagnostic connector (2-15) to MCU (pin 16)
 56B - vacuum switch assembly to diagnostic connector (2-15)
 57A - high altitude jumper to MCU (pin 11)
 57B - high altitude jumper to diagnostic connector (2-3)
 58A - MCU (pin 44) to idle vacuum solenoid
 58B - idle vacuum solenoid to diagnostic connector (2-2)
 59A + solenoid to diagnostic connector (1-5)
 59B + idle relay switch to solenoid

001203

An General Division

TO: Mr. R. M. Johnson

LOCATION: AMG/Livonia

COPY TO:
J. A. Armour
K. M. Jordan
A. W. MacDonald
F. Marano, Jr.
F. I. Masten
G. E. Stuart
D. P. WeiherFROM: *[Signature]*
G. derPillbosian
Principal EngineerLOCATION: AMG/Livonia
#8039

bcc: P. Rosenak

SUBJECT: Trip Report
Hartford, CT
FJ8C Engine
Compartment Fire

DATE: October 25, 1985

We were recently informed of an engine fire which occurred on an FJ8C vehicle sometime during early August 1985. Subsequent information revealed the vehicle involved was 3291504 located in Hartford, CT with 5210 miles recorded on its odometer.

The subject vehicle was examined by the writer on October 15, 1985 at Lipman Motors, AMC dealership where it had been sent for repairs by the USPS. No definitive determinations could be made as a result of this examination.

The extent of fire damage was very limited and was concentrated at the left rear of the engine. Vacuum hoses and wiring harness were damaged as was the rocker cover. Unfortunately, the wiring harness and vacuum hoses had been disturbed and the rocker cover had already been replaced prior to this examination. Photographs were taken and clearly depict the limited damage.

Ash residue is concentrated on top of the #5 & 6 intake manifold. Vacuum hoses which would normally be located in this area were partially burned. PCV hoses were intact.

Wiring harness loom was almost completely destroyed rearward of the rear "P" clamp. The top half of the loom was destroyed forward of the clamp for a distance of approximately 5".


The stepper motor connector was intact and most of the wire insulation remained, however, the loom was totally destroyed from the taped end forward as described above.


All wire insulation, including connectors, was totally destroyed by fire on the ground, temperature gauge sending unit, and triple solenoid valve circuit wires in this area.

In addition, heat damage was noticeable on the TES, PCV shut off solenoid and WOT switch wires, as well.

GDP/jse
GDP00000

001204





10/14/85 Called to Jean Motors
John Marinelli - Shop dispatcher

- Value cover ~~not~~ removed - only work done

~ Wiring harness ~ 8/12/85 fire occurred
according to John M. S

→ vehicle is in storage yard - waiting receipt
of wiring harness - 9/13 ordered - 5995769-

1 1/2 hour ride from airport.

001217

Paul Kosak called 11 30 10/8/85
about

→ Hartford, Conn. vehicle
fire status in our hands
- 589 5769 -

Order placed out thru contractor
to front end
plastic valve cover burned
vehicle not started
wiring harness intact on
vehicle
wiring harness burned

contents of Hartford fire in Paul's possession. He will
send them express
mail

LIPMAN MOTORS

450 HOMESTEAD AVE

HARTFORD CT

EDDIE LEONARD SERVICE WRITER
(203) 522-8225

001268

FIELD DEFICIENCY REPORT

AM GENERAL CORPORATION
South Bend, Indiana 46680cc Alex
Leo
Galie

F-786 SB P1

SERVICE REPRESENTATIVE Fred I. MastenVEHICLE SERIAL NO. 3291504DATE OF INSPECTION 10-7-85

VEHICLE REG. NO. _____

AGENCY U.S.P.S

ACCEPTANCE DATE _____

CITY Hartford STATE CT.MILEAGE 5,210 COMPONENT S/N _____REPORTING OFFICER Paul RosenakMODEL FV-8C COMPONENT S/N _____

DEFICIENCY: Under hood fire - extensive -
Valve cover melted - emission hoses
wiring harness etc - Reported
by Paul Rosenak on 10-7
Mr. Rosenak stated fire occurred
on 8/10/85 and that the
vehicle was at the dealer for
repairs Lipman AMC/Jep. 203-522-8225
PROBABLE CAUSE: Unknown at this time Ed. Leonard.

FAILURE OCCURRED (Type of Service): Routine operation of
vehicle

CORRECTIVE ACTION TAKEN:

None - Relayed info to Galie.
Livonia

WARRANTY: YES _____

NO (circled)



DISPOSITION OF ORIGINAL PARTS _____

DISTRIBUTION

Original and Two Copies to AM General Corporation, South Bend, Indiana.
One Copy Retained Representative File.

Use Second Lined Sheet for Additional Remarks

001209



FIELD OFFICIAL'S REPORT

AN GENERAL CORPORATION
South Bend, Indiana 46530

F-106 88-1

SERVICE REPRESENTATIVE <u>B. Brant - N. Vetter</u>	VEHICLE SERIAL NO. <u>3291818</u>
DATE OF RECEIPT <u>Report 7.10.85</u>	VEHICLE REG. NO. <u>N/A</u>
AGENCY <u>US Post Office VME</u>	ACCEPTANCE DATE <u>—</u>
CITY <u>Pittsburg</u> STATE <u>Pa.</u>	MILEAGE <u>4,130</u> COMPONENT S/N <u>N/A</u>
REPORTING OFFICER <u>Tom Sarge</u> <u>Supervisor</u>	MODEL <u>F39C</u> CONTRACT <u>67456</u>

DEFICIENCY Under the hood fire

PROBABLE CAUSE: Leaking Diesel leaked this appeared to
be a fuel fire in the area of the Governor.
More investigation was conducted to get to bottom this as
All fire damage has been cleaned up and vehicle is put up to repair

*FAILURE OCCURRED (Type of Break): Normal Post Office Service

CORRECTIVE ACTION TAKEN: IME Sent Vehicle to AMC Dealer for
repair

WARRANTY YES ☒ NO ☐

DISPOSITION OF ORIGINAL PARTS per. record by

ILLEGIBLE

001212

DISTRIBUTION
Original and Two Copies to All General Corporation, South Bend, Indiana.
One Copy Retained in Manufacturer's File.

Use Bottom Unlined Space for Additional Remarks